

# Case History



Product Series: RA500

Country	Customer	Job / Location	Description	Date
UK	Gemini	North sea platform	Internal vessel lining	2008
UK	Gemini	North sea platform	Pressure vessel lining	2008
UK	Salamis	Clyde platform	Vessel Lining	2008
UK	Hertel	BP Dalmany (Tank 804)	Internal tank lining	2008
UK	Salamis	Tarton platform	Internal Vessel Lining	2008
UK	Salamis	Tarton platform (Talisman)	Internal Vessel Lining	2008
UK	Salamis	Uk Offshore platform	Internal vessel coating	2007
UK	Independent Industrial Services	UK Hydro station	Tank repair	2007
UK	Salamis	UK Offshore oil platform	Vessel repair	2007
UK	PCIS	Cramlington Factory	Bund coating	2007
UK	PTCS			2007
UK	Independent Industrial Services	UK	External pipe work	2007
UK	Salamis	Flotta Oil terminal	Internal tank coating	2007
UK	Survair coating services Ltd	Volume grant distillery	Internal floor coating	2007
UK	Salamis	Flotta Oil terminal	Internal tank coating	2007
UK	Spray Glass	UK		2007
UK	Hertel	BP Grangemouth tank T804	External tank coating	2007
U.A.E	Enterprise Engineering services Ltd	Hydro station	Internal pipe work	2007
UK	Hertel	BP Finnat (Ocean team)	Internal Tank Lining (Crude oil storage)	2007
UK	Hertel	BP Kenniel	Internal tank lining	2007
UK	Salamis	UK Oil platform	Vessel repair	2007
UK	Salamis	Flotta oil terminal	Internal vessel coating	2007
UK	Murphys Waves Ltd.	Tenerif	Wave machine	2007
UK	Hertel	BP Grangemouth	Internal tank lining	2007
UK	Salamis	Clyde oil platform	Offshore Aberdeen	2006
UK	RBG	Blue holm FPSO	Pipe works and decks	2006
Bahrain	US Marin	Bahrain	Pump and tank lining equipments	2006
UK	RBG	Blue holm FPSO	Decks	2006
UK	RBG	Blue holm FPSO	Vessel and pipe works	2006
UK	Metal-Brite	Lanzerati (Spain)	Wave machine	2006
UK	Metal-Brite	Lanzerati (Spain)	Wave machine	2006
UK	Metal-Brite	Lanzerati (Spain)	Wave machine	2006

# Case History

Product Series: RA500



Country	Customer	Job / Location	Description	Date
Bahrain	US Marin	Bahrain	Pump coatings	2006
UK	Salamis	Piper oil platform	Internal repair to vessel	2006
UK	Hertel	BP Kenniel	Tank internals	2006
UK	Hertel	BP Kenniel	Tank internals	2006
Belgium	Alcotec	Belgium	Pump, valve & tank repair	2006
UK	Metal-Brite	Lanzerati (Spain)	Wave machine	2006
UK	Race horses	England	External coating for horse box	2006
UK	Gemini Corrosion services Ltd	Aberdeen	Tank externals	2006
UK	Salamis	Flotta oil terminal	Tank internals	2006
UK	Salamis	Flotta oil terminal	Tank internals	2006
UK	Deborah Services Limited	BP Grangemouth	Concrete floor	2006
UK	RPM		Structural steel	2006
UK	Hertel	BP Grangemouth	Tank internals	2006
UK	RBG	Blue holm FPSO	Ballast tank repair	2006
UK	Metal-Brite		Wave machine	2006
UK	RBG	Blue holm FPSO	Ballast tank repair	2006
UK	EDF Energy		Pipe work	2006
UK	B&P Decorator		Padeling pool	2006
UK	Salamis	Orkney Island	Tank work	2006
UK	RBG	Blue holm FPSO	Tank work	2006
UK	Deborah Services Limited	BP Grangemouth	Concrete plynth	2006
UK	RBG	Blue holm FPSO	Tank internals	2006
UK	Talisman energy	FPSO Blue-holm	Fuel storage tank	2006
UK	Hertel	BP Kenniel	Tank internals	2006
UK	RBG	Blue holm FPSO	Tank	2006
UK	Salamis	Orkney island	Tank work	2006
UK	Coastgroup Ltd.		Steel piles	2006
UK	PCIS		Concrete bund	2006
UK	Rigblast		Tank externals	2006
UK	Corecut		Concrete pipe	2006
UK	Rigblast		Pipe externals	2005
UK	B&P Decorator	Local authority	Padeling pool concrete	2006

# Case History



Product Series: RA500

Country	Customer	Job / Location	Description	Date
UK	B&P Decorator	Local authority	Padeling pool concrete	2006
UK	B&P Decorator		Swimming pools	2005
UK	Salamis		Vessel internals	2005
UK	Shepherd Construction Ltd.			2005
UK	corecut		Concrete pipe	2005
UK	US Marin			2005
Bahrain	Marine & Ind Pump Repair		Tank lining	2005
Malaysia	Huntech			2005
UK	Mr. Ernest A Baade			2005
UK	US Marin			2005
Belgium	Alcotec	Belgium	Various	2005
UK	B&P Decorator	BMW Factory	Structure	2005
UK	Trac International			2004
UK	Materials Enhancement Ltd			2004
Bahrain	Marine & Ind Pump Repair		Tank lining	2004
UK	Mitsui Babcock	UK	Outlet duct	2004
Belgium	Alcotec	Belgium	Various	2004
UK	Mitsui Babcock	UK	Outlet duct	2004
UK	US Marin			2004
UK	Mitsui Babcock	Longannat power station	Drains rec pipework	2004
UK	Kee Services Ltd	England	Repair of GRP waste tank	2004
UK	US Marin			2004
UK	Mr. Tytler			2004
UK	London swimming pool Ltd	England		2004
Bahrain	Marine & Ind Pump Repair		Tank lining	2004
Bahrain	Marine & Ind Pump Repair		Tank lining	2004
UK	North British Distiller	Scotland	Internal Coating of Grain Tank	2004
UK	US Marin			2004
Belgium	Alcotec	Belgium	Various	2004
UK	Watermotive			2004
UK	Watermotive			2004
Belgium	Alcotec	Belgium	Various	2004

# Case History



Product Series: RA500

Country	Customer	Job / Location	Description	Date
UK	US Marin			2004
Belgium	Alcotec	Belgium	Various	2004
Bahrain	Marine & Ind Pump Repair		Tank lining	2003
Bahrain	Marine & Ind Pump Repair		Tank lining	2003
UK	US Marin			2003
UK	US Marin			2003
UK	NEL	East Kilbride (Scotland)	Internal Lining of Water tank	2003
UK	US Marin			2003
UK	Salamis	Offshore oil instalation	Tank work	2003
Belgium	Alcotec	Belgium	Various	2003
UK	US Marin			2003
UK	US Marin			2003
Romania	Poly Delta Chemicals			2003
UK	US Marin			2003
UK	Watermotive			2003
UK	Rigblast	Offshore oil instalation	Pipe work	2003
UK	Alcan Primery Metal	UK power stations	Refurbishment of chute	2003
UK	Rigblast	Offshore oil instalation	Vessel repair	2003
UK	Rigblast	Offshore oil instalation	Pipe work	2003
Belgium	Alcotec	Belgium	Various	2003
UK	Materials Enhancement Ltd	British sugar	Pipe work	2003
Belgium	Alcotec	Belgium	Various	2003
UK	Salamis	Offshore oil instalation	Tank work	2003
UK	Salamis	Offshore oil instalation	Tank work	2003
UK	US Marin			2003
Belgium	Alcotec	Belgium	Various	2003
UK	Garrard Ltd			2003
UK	Alcan Primery Metal	UK power stations	Refurbishment of chute	2003
UK	Alcan Primery Metal	UK power stations	Refurbishment of chute	2003
UK	US Marin			2002
UK	Scott (MR A. Scott)	milking pallour	Walls and floor completely coated	2002
UK	Scott (MR A. Scott)	milking pallour	Walls and floor completely coated	2002

# Case History

Product Series: RA500



Country	Customer	Job / Location	Description	Date
Bahrain	Marine & Ind Pump Repair		Tank lining	2002
UK	Specialist Industrial Coatings			2002
UK	US Marin			2002
UK	Enterprise Engineering services Ltd	Scotland	Insitu Internal Pipe Coating	2002
Bahrain	Marine & Ind Pump Repair		Tank lining	2001
Bahrain	Marine & Ind Pump Repair		Tank lining	2001
Bahrain	Marine & Ind Pump Repair		Tank lining	2001
UK	US Marin			2001
UK	US Marin			2001
Bahrain	Marine & Ind Pump Repair		Tank lining	2001
UK	Barrie Ltd			2001
UK	CAPE	British Gas Armada	Oil platform	2000
UK	US Marin			2000
UK	Ross-Shire Eng	Loch Gair power station (Scotland)	Internal Pipe Refurbishment	2000
India	Aashish Coating Technologies PVT	India		2000
UK	Induction Heat Treatment Services		External tank coating	2000
UK	Rigblast	Offshore oil instalation	Vessel repair	2000
India	Aashish Coating Technologies PVT	India		2000
India	Aashish Coating Technologies PVT	India		2000
India	Aashish Coating Technologies PVT	India		1999
Bulgaria	Kemco Bulgaria	Bulgaria		1999
UK	CAPE	British Gas Armada	Oil platform	1999
India	Aashish Coating Technologies PVT	India		1998
Singapore	BEI HAI - Singapore			1998
India	Aashish Coating Technologies PVT	India		1998
Singapore	BEI HAI - Singapore			1998
India	Aashish Coating Technologies PVT	India		1997
India	Aashish Coating Technologies PVT	India		1997