Case Study



Client:	d'Amico	Industry: Marine
Vessel:	Bulk Carrier	Date: 2011
Location:	UAE	Products: Epo-chem™ RS 500P & RA 500M

Overview

The topside tanks onboard the Bulk Carrier had previously been coated with coal-tar epoxy. Areas within these tanks were showing signs of corrosion damage and required to be patch repaired.

Challenge

Finding a coating system which was compatible with coal-tar epoxies. Also, due to equipment and supply restrictions, abrasive blasting or hydro blasting could not be used to conduct surface preparation.

Solution

Mechanical power tooling was utilised as the surface preparation method to remove all the loose rust and existing damaged coating. This was followed by a fresh water wash. One coat of solvent-free, wet & rust tolerant epoxy Epo-chem™ RS 500P. This was followed by one topcoat of solvent-free, wet tolerant epoxy Epo-chem™ RA 500M.

Outcome

The unique characteristics of **Epo-chem™ RS 500P** allowed the system to be applied with no compatibility issues and with strong adhesion to the coal-tar epoxy.

Benefits

- Solvent-free
- No grit blasting
- No dehumidification required
- No disruption to others working nearby (including hot work)
- Reduced H&S and Fire Precaution
- Reduced contract duration
- Compatibility with coal-tar epoxy
- Work carried out by riding crew

Continued overleaf





Photographs

• Nos. 1-2 Before Application

*This Project was carried out by Charisma Ship Maintenance LLC, Dubai

Rev: July 2018 Ref: M15

3

















Photographs

• Nos. 3-7 Completed Application

İ.....i

East Shawhead Industrial Estate ML5 4XD Coatbridge United Kingdom

Email: sales@chemcoint.com Web Site: www.chemcoint.com